



December 17, 2018

Subject: Hilti S-SLC 02 M HWH and ICC-ES ESR-3693 Label

To whom it may concern,

Hilti S-SLC 02 M HWH side-lap screws which are manufactured at Hilti's approved supplier have valid ICC-ES evaluation reports, ESR-3693, ESR-2776 and ESR-2197 as of the date of this letter.

Hilti recently discovered the manufacturing location of this approved supplier was not in ICC-ES's system for ESR-3693. Hilti has since added ESR-3693 to the quality document BHB-ICC ES-200 for this supplier. In addition, the approved supplier's manufacturing location is being added to ICC-ES ESR-3693 through an open technical revision ESR-3693-03.

Please feel free to contact our Engineering Technical Services department for more information or any questions.

Hilti Engineering Technical Services – United States
(877) 749-6337 toll free
hnatechnicalservices@hilti.com

Hilti Engineering Technical Services – Canada
(800) 363-4458 toll free
CATechnicalServices@hilti.com

Hilti Inc.
7250 Dallas Parkway, Suite 1000
Plano, TX 75024

1-800-879-8000
www.hilti.com